

# UNCLASSIFIED

AD NUMBER
AD827909
NEW LIMITATION CHANGE
TO Approved for public release, distribution unlimited
FROM Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; 28 FEB 1968. Other requests shall be referred to Air Force Materials Lab., Wright-Patterson AFB, OH 45433.
AUTHORITY
AFML ltr, 12 Jan 1972

THIS PAGE IS UNCLASSIFIED

909

AD-602



# RECENT DEVELOPMENTS

## Corrosion and Compatibility

February 23, 1968

MAR 5

This document is subject to control of the Department of Defense and is not to be released to foreign government, organization, or individual without prior approval of the Department of Defense.

### GENERAL

The Proceedings of the Air Force Materials Laboratory Fifteenth Anniversary Conference on Corrosion of Military and Aerospace Equipment, held in Denver May 23-25, 1967, have been issued.<sup>(1)</sup> Some seventy papers covering all aspects of corrosion are reproduced in their entirety. The individual papers were reviewed in the two previous DMIC Reviews on Corrosion and Compatibility dated October 11, 1967, and December 15, 1967.

A literature survey on raindrop erosion has been released by Arlington Arsenal.<sup>(2)</sup> The survey concludes that rain erosion is expected to be very serious with most nose-cone materials when the missile nose-cone radius is less than 0.5 feet and it is passing through rain at velocities greater than 3000 ft/sec. Equations are available for estimating the penetration of individual raindrops into ductile metals and ablating surfaces at velocities to 30,000 ft/sec. Rain-erosion damage is directly related to the thickness of the molten ablative material on the nose cone is increased. Nose-cone splices have been effective in reducing rain-erosion damage at velocities of a few thousand feet per second.

The effect on corrosion resistance of boron-fiber strengthening of aluminum, copper, and nickel has been reported by Avco.<sup>(3)</sup> The boron either had no effect on, or slightly enhanced, the corrosion rates of these materials in chloride solutions or in air oxidation. In addition, the aluminum-copper composites showed a somewhat greater corrosion rate in different solutions at pH 8 and a slightly decreased rate at pH 4 and 10 (as compared with those without boron). The presence of boron in nickel accelerated the corrosion in aluminum sulfate solutions.

The effect of inhibitors on the corrosion of aluminum, magnesium, stainless steel, and titanium in  $H_2O_2$  containing added water has been studied at the Aerospace Corporation.<sup>(4)</sup> Corrosion tests were conducted at 15.5 C (59.9 F) for periods ranging from 15 to 60 days. Ammonium fluorosulfonate ( $NH_4FSO_3$ ) appeared to be the best of the inhibitors investigated. Other promising inhibitors were phosphorus pentafluoride, phosphorus trifluoride, and potassium fluorosulfonate. The long-term effects of the inhibitors on corrosion performance and their effects on propellant performance were not studied.

Impact data for aluminum and titanium alloys are being determined by McDonnell Douglas as part of a study on the engineering behavior of tankage materials in liquid propellants.<sup>(5)</sup> Standard ASTM

room-temperature tests (at 70 ft-lb) indicated that 2014-T6 aluminum was not impact sensitive in  $H_2O_2$  or liquid fluorine but was impact sensitive in  $ClF_3$  at temperatures between -50 C (-58 F) and the boiling point, -14 C (6.8 F). Modified GMA room-temperature impact tests revealed that 11-SAl-47 alloy was not impact sensitive in  $H_2O_2$ , but was impact sensitive at 42.5 ft-lb in  $ClF_3$  at -14 C.

### CORROSION OF ALUMINUM ALLOYS

#### General

The effect of a deionized water rinse after sulfuric acid-sodium dichromate treatment on the adhesive-bonding characteristics of 2024 aluminum has been studied by Picatinny Arsenal.<sup>(6)</sup> Immersions greater than 15 minutes in deionized water at 60 C (140 F) produced an iridescent film on the aluminum and a subsequent loss in adhesive bondability. A hydrated oxide layer ( $Al_2O_3 \cdot 3H_2O$ ) 1000 A thick was found on the surface of these specimens. Multivalent compounds added to the water were found to preferentially absorb into the aluminum oxide and block the entrance of water, thereby preventing hydration of the oxide. The addition to the deionized water (at pH below 5) of multivalent compounds such as  $H_2SO_4$ ,  $H_2SO_3$ ,  $CrCl_3$ ,  $Na_2CrO_4$ ,  $Na_2SO_4$ ,  $FeCl_3$ , and  $FeCl_2$  was recommended to give good bonding surfaces. Alkaline compounds such as  $NaOH$ ,  $Na_2CO_3$ , and  $K_2CO_3$  were not recommended because they attack and discolor the aluminum.

#### Stress-Corrosion Cracking

Research on an accelerated stress-corrosion test for aluminum alloys is continuing at Kalpat.<sup>(7)</sup> A continuous immersion in 1 percent NaCl-2 percent  $K_2Cr_2O_7$  solution at pH 4 and 60 C was found to be effective in separating the tempers of 2024, 2219, and 7075 alloys that exhibit borderline and maximum resistance to cracking in the short-transverse direction of fabrication. The salt-dichromate test made these separations in 1 week or less compared with 30 days in alternate immersion in 3.5 percent NaCl solution. Coring specimens gave the best correlation between the two test methods. Tensile specimens (1/8-inch diameter) did not always give an aggressive test in the salt-dichromate tests specifically with the tempers of the 2219 and 7075 alloys which exhibited borderline resistance to cracking.

Research on the exfoliation and stress-corrosion characteristics of high-strength heat-treatable aluminum alloy plate has been summarized by Alcoa.<sup>(8)</sup> Specimens were evaluated in marine and industrial atmospheric tests and in acidified



dissolved titanium increased the corrosion resistance of ferronickel-extracted magnesium by a factor of 5 to 10. Saturation of electrolytic magnesium with titanium increased its corrosion resistance by a factor of 15 to 20, presumably because of the removal of iron.

#### CORROSION OF NICKEL-BASE ALLOYS

Half-cell potentials have been measured by the Marine Engineering Laboratory for nickel-base superalloys, several pure metals, nickel-chromium binary alloys, and several intermetallic compounds in molten NaCl and Na<sub>2</sub>SO<sub>4</sub> at 1650 F.<sup>(17)</sup> Platinum was used as the reference electrode. Potentials for pure chromium and alloys containing more than 15 wt% chromium exhibited a marked positive change with time in the Na<sub>2</sub>SO<sub>4</sub>, but only a slight positive change in NaCl. The behavior in Na<sub>2</sub>SO<sub>4</sub> was correlated with the formation of protective Cr<sub>2</sub>O<sub>3</sub> oxide on the specimens, while that in NaCl was related to the rapid attack on chromium-containing alloys in this medium.

A summary report on the hot corrosion of nickel-base alloys has been issued by Allison Division of General Motors.<sup>(18)</sup> Each test consisted of 500 cycles at 1700, 1800, 1900, or 2000 F. A cycle consisted of a 0.5-minute spray of 1 percent sodium sulfate solution between 1.5-minute heating periods. A regression equation was derived which related metal loss to alloy chemistry. Chromium and aluminum were beneficial to corrosion resistance whereas tungsten and molybdenum were detrimental. The order of decreasing corrosion resistance of alloys studied was FDL 163, IN-728M, Alloy 713C + 2Cr + Y, Alloy 713 + 2Cr, Inco 717, Alloy 713C, Mar-M241 (14.6Cr), IN-100, GMR-235, and Mar-M235.

One year's results of a study of the hot corrosion of nickel-base and cobalt-base superalloys have been summarized by General Electric.<sup>(19)</sup> Alloys were exposed 500 to 1000 hours at 1600 to 2050 F to the exhaust gases from diesel fuel (18S) which were injected with 5 ppm sea salt. Sulfidation was severe at 1600 to 1750 F, but was not a problem at temperatures above 1750 to 1800 F, presumably because Na<sub>2</sub>SO<sub>4</sub> vaporizes at these temperatures. At 1600 to 1750 F, the commercial cobalt-base alloys were more corrosion resistant than the commercial nickel-base alloys. The best alloys were I-40 and Hastelloy X. The most corrosion-resistant cobalt-base alloys at 1900 to 2050 F were MELCO-2-9 and -10.

At General Electric, a mechanism study of the hot corrosion of superalloys in hot gases containing NaCl and SO<sub>2</sub> led to the conclusion that hot corrosion was the result of increased oxidation caused by the removal of chromium from the alloy matrix by the formation of chromium-rich sulfides.<sup>(20)</sup> As these sulfides become oxidized, the sulfur penetrated more deeply into the alloy, creating susceptibility to faster oxidation in these areas. Aluminum, cerium, and titanium additions to nickel-base alloys reduced corrosion in some instances, whereas cerium, lanthanum, and yttrium were beneficial in cobalt-base alloys.

#### CORROSION OF TITANIUM

##### General

The English have studied the ignition and burning of titanium alloys in connection with fires

in the titanium compressor stages of gas turbine engines.<sup>(21)</sup> Some 39 binary alloys were ignited in oxygen. The ignition temperature of pure titanium was found to be 1417 C (2583 F). Significant changes in ignition temperatures due to alloying are summarized below.

Alloy Composition, wt%	Difference from Ignition Value for C. P. Titanium, °C
1.0 carbon	+95
6 copper	+63
5 iron	+70
34 molybdenum	+95
6 nickel	+63
0.1 sulfur	+98
0.5 silicon	+78
2 silicon	+80
46 tantalum	+98
30 tungsten	+98
10 silver	-54
13 copper	-64
27 manganese	-117
0.25 sulfur	-57
12 tin	-113
22 tin	-107
31 zirconium	-287

Although aluminum in titanium had no significant effect, the injection of aluminum powder into the stream lowered the ignition temperature by more than 100 C, thus tending to confirm that fires in titanium compressor blades are caused by rubbing against debris from aluminum blades in earlier stages of the compressor.

##### Stress-Corrosion Cracking

The proceedings of the 1-day seminar at Battelle's Columbus Laboratories on March 6, 1967, dealing with accelerated crack propagation in titanium has been issued by the Defense Metals Information Center.<sup>(22)</sup> Included are 15 informal papers and discussions by participants on the stress-corrosion cracking of titanium alloys by methanol, halogenated hydrocarbons, and other solutions.

The corrosion behavior of Ti-6Al-4V in commercial Freon IF with and without 0.3 ppm chlorine gas has been studied by Aerospace Corporation.<sup>(23)</sup> Metallographic analysis and mechanical-property measurements revealed no cracking after 72 hours' exposure of welded and nonwelded tensile specimens stressed to 80 percent of the 0.2 percent offset yield strength.

The stress-corrosion-cracking behavior of some 30 commercial titanium alloys has been determined by the Naval Research Laboratory to provide guideline information and determine the underlying principles that affect stress-corrosion cracking.<sup>(24)</sup> Tests were conducted in 3.5 percent NaCl solution with precracked cantilever beam specimens. Weld specimens were included in the program. The results indicated that there was no correlation between mechanical properties and susceptibility to stress-corrosion cracking.

Fracture toughness and the stress-corrosion cracking of welded 1-inch thick titanium-alloy specimens has also been studied by the Naval Research Laboratory.<sup>(25)</sup> The stress-corrosion tests were performed in 3.5 percent NaCl solution using

precracked cantilever beam specimens. Alloys studied included Ti-6Al-4V, Ti-6Al-2Mo, Ti-6Al-6V-2Sn, Ti-6Al-3V-1Mo, Ti-7Al-2Cu-1Fe, Ti-7Al-1Mo-2V, Ti-6Al-2Sn-2V, Ti-7Al-2Mo, and Ti-6Al-2Cu-1Fe-0.8Mo. There did not appear to be any correlation between fracture toughness and stress-corrosion-cracking resistance of the materials.

Studies on the effect of hydrogen and microstructure on the stress-corrosion cracking of titanium alloys are continuing at Douglas.<sup>(25)</sup> Different amounts of hydrogen (27 and 100 ppm) were introduced in Ti-6Al-1Mo-1V at 1800, 1900, and 2000 F, followed by an air quench. Subsequent tests with notched specimens in a 3 percent NaCl solution revealed that the 1800 F solution treatment was susceptible to stress-corrosion cracking at these hydrogen concentrations, but that the 1900 and 2000 F treatments were not.

The morphology of stress-corrosion cracks in titanium alloys has been studied by Boeing.<sup>(27)</sup> Precracked specimens were exposed to 3.5 percent NaCl solution. Comparisons of electron fractographs of cracks and electron micrographs of the structures in alpha-beta Ti-6Al-1Mo-1V and Ti-6Al-4V alloys revealed a cleavage failure in the alpha phase and a ductile fracture in the beta phase. Coplanar dislocation arrangements were found in Ti-6Al-4V and Ti-6Al-1Mo-1V but not in Ti-6Al-2Mo-1V, which correlated qualitatively with susceptibility of these alloys to cracking under these exposure conditions.

The stress-corrosion-cracking behavior of Ti-6Al-1Mo-1V alloy in NaCl and methanol is being studied at the Ohio State University.<sup>(28)</sup> Slow crack growth in precracked tensile-type specimens occurred over a range of +960 to 2040 av (SIC) in saltwater, suggesting that hydrogen evolution is not a necessary factor in crack propagation. Current densities of 1.5 amp/cm<sup>2</sup> were estimated during the active propagation of a rapidly advancing crack in methanol-water-salt solution.

The influence of microstructure on the stress-corrosion fracture path in titanium alloys is being studied at Boeing.<sup>(29)</sup> Results obtained with precracked notched specimens in 3.5 percent NaCl solution indicated stress-corrosion-cracking susceptibility in the alpha phase in Ti-6Al-1Mo-1V, Ti-6Al-4V, and Ti-6Al-3Mo-1V, in martensite in Ti-2Al-2.5Sn, and in the beta phase in Ti-13V-11Cr-3Al. Stress-corrosion-cracking susceptibility could not be correlated with any one or combination of microstructural features. Immunity to cracking (at least in the three immune phases of Ti-6Al-1Mo-1V alloy) appeared to be related to high molybdenum and vanadium content and low aluminum and oxygen content. Thus, the basic cracking mechanism was concluded to be surface controlled.

Boeing has also used wedge-force loading of center-cracked sheet specimens to determine whether stress-corrosion cracking depends on an applied crack-tip stress-intensity factor or on net-section stresses.<sup>(30)</sup> With this loading, crack extension causes a decreasing stress-intensity factor at the crack tip, while the net-section stresses increase. Thus, when the stress-corrosion crack growth is arrested in this specimen, the dependency on stress intensity is indicated. The stress intensity at arrest for Ti-6Al-1Mo-1V alloy agreed well with  $K_{ISCC}$

values determined by other techniques that establish crack initiation thresholds through multiple tests.

Research on the stress-corrosion cracking of notched titanium in seawater is continuing at the Marine Engineering Laboratory.<sup>(31)</sup> Results to date with titanium-aluminum alloys indicate that a critical amount of coherent lath precipitate will cause seawater stress-corrosion cracking. As the quantity of lath was increased, the sensitivity of the alloy to cracking also increased. The reduction of aluminum and oxygen contents and the addition of isomorphous beta stabilizers suppressed the formation of lath and improved the resistance of titanium-aluminum alloys to cracking in seawater. Minor additions of less than 0.5 percent of the eutectoid formers, nickel, iron, and manganese, increased the cracking sensitivity of Ti-7Al-2Cu-1Fe, while the addition of 0.07 percent palladium made this same alloy resistant to cracking. A minimum of 0.250 percent oxygen in unalloyed titanium induced cracking in seawater.

The effect of high-altitude supersonic airflow conditions on the hot-salt cracking of titanium has been investigated at Lockheed.<sup>(32)</sup> Wind-tunnel tests were conducted for a total of 50 hours' exposure under such 2.5 supersonic flow conditions at a pressure equivalent to 70,000-ft altitude and temperatures of 600 and 700 F. Duplex-annealed Ti-6Al-1Mo-1V and mill-annealed Ti-6Al-4V alloys were used in self-stressed specimens. The results demonstrated that these simulated supersonic-flight conditions did not eliminate hot-salt cracking. However, the cracking was not as severe as in static laboratory tests at the same temperature, presumably because of the removal of some of the salt coating by the high velocity air.

A summary report has been issued by Northrop on the hot-salt stress-corrosion cracking of Ti-6Al-4V, Ti-6Al-1Mo-1V, Ti-13V-11Cr-3Al, Ti-6Al-6V-2Sn, and Ti-6V alloys.<sup>(33)</sup> At 450 F, only mill-annealed Ti-6Al-1Mo-1V alloy exhibited cracking. Threshold values for cracking were found to be between 0.35 and 0.50 of the yield strength at 550 F and between 0.25 and 0.45 of the yield strength at 650 F. At stress levels just above threshold values, crack nucleation times were much longer with thermal cycling than during continuous exposure at temperature. Studies on the kinetics of the formation and decomposition of TiCl<sub>2</sub> on NaCl-coated titanium alloys indicated the possibility of eliminating the hot-salt cracking of titanium alloys above 550 F by thermal cycling in such a manner that the time at temperature is less than that required to form TiCl<sub>2</sub> and that the time at room temperature is greater than that required to decompose TiCl<sub>2</sub>.

#### REFERENCES

- (1) Meyer, F. H., Jr., Conference Chairman, "Proceedings of the Air Force Materials Laboratory Fiftieth Anniversary", Report AFML-TR-67-329, Technical Conference on Corrosion of Military and Aerospace Equipment, Denver, Colo., May 23-25, 1967.
- (2) Wheelahan, E. J., "State-of-the-Art Survey of Raindrop Erosion", Report No. R5-TR-67-13 (1958-September, 1964), Redstone Arsenal, Ala. (November 1967) DHC No. 70919.

- (3) Porter, W. C., and Moliff, E. G., "Corrosion of Boron-Metal Composites", Avco Corporation, Lowell, Mass., paper presented at the 12th National SAMPE Symposium, held at Anaheim, Calif., October 10-12, 1967, DMIC No. 70564.
- (4) Hess, F. D., "Studies of Corrosion Inhibitors for Nitrogen Tetraoxide", Report TR-0158(3210-10)-4, Aerospace Corporation, El Segundo, Calif., Contract F04695-67-C-0158 (September 1967) DMIC No. 71192.
- (5) Preliminary information reported by McDonnell Douglas Corporation, Newport Beach, Calif., under NASA Contract NAS 7-488.
- (6) Wegman, R. F., Bodnar, W. M., and Bodnar, M. J., "Effects of Deionized Water Immersion of Prepared Aluminum Surfaces on Adhesive Bondability", Report 3495 (AD 652358), Picatinny Arsenal, Dover, N. J. (May 1967) DMIC No. 70351.
- (7) Preliminary information reported by Kaiser Aluminum and Chemical Corporation, Spokane, Wash., under NASA Contract NAS 8-20283.
- (8) Lifka, B. W., Sprawls, C. O., and Kaufman, J. G., "Exfoliation and Stress-Corrosion Characteristics of High Strength, Heat Treatable Aluminum Alloy Plate", Corrosion, 23 (11), 335-342 (November 1967) DMIC No. 70956.
- (9) Turley, R. V., Dash, E., and Avery, C. H., "Stress Corrosion Susceptibility of Welded Aluminum Alloys", Final Report AFML-TR-67-291, Douglas Aircraft Company, McDonnell Douglas Corporation, Long Beach, Calif., Contract AF 33(615)-3419 (August 1967) DMIC No. 71083.
- (10) Hunter, M. S., "Study of Crack Initiation Phenomena Associated With Stress Corrosion of Aluminum Alloys", First Annual Report, Alcoa Research Laboratories, New Kensington, Pa., Contract NAS 8-20396 (September 28, 1967) DMIC No. 70537.
- (11) Preliminary information reported by Rocketdyne Division, North American-Rockwell Corporation, Canoga Park, Calif., under U. S. Navy Contract N00019-67-C-0466.
- (12) Miller, P. D., and Boyd, W. K., "Corrosion of Beryllium", DMIC Report 242, Defense Metals Information Center, Battelle Memorial Institute, Columbus Laboratories, Columbus, O., Contract AF 33(615)-3408 (December 11, 1967).
- (13) Preliminary information reported by the U. S. Naval Applied Science Laboratory, Brooklyn, N. Y.
- (14) Williams, M. F., "Outdoor-Exposure Tests of Induction-Heated Tubing at Vandenberg Air Force Base", Report LMSC-AS41472 (AD 819043), Lockheed Missiles & Space Company, Sunnyvale, Calif., Contract AF 04-(695)-939 (May 23, 1967) DMIC No. 70548.
- (15) Brush, E. G., "The Effect of Cathodically-Charged Hydrogen on Crack Generation in Type 304 Stainless Steel", USAEC Report GEAP-3415, General Electric Company, Pleasanton, Calif., Contract AT(04-3)-189 (March 1967) DMIC No. 70979.
- (16) Viskarew, A. F., Barzovik, I. A., and Kelmets, G. G., "Influence of Titanium on the Corrosion Resistance of Magnesium", Protection of Metals, 3 (2), 203-204 (March-April 1967) DMIC No. 70827.
- (17) Doering, M. von E., "Behavior of Nickel-Base Superalloys in Molten Salts", Report 2468 Naval Ship Research and Development Center, Annapolis, Md. (September 1967) DMIC No. 70302.
- (18) Ryan, K. M., Kildsig, J. R., and Hamilton, P. E., "Investigation of Hot Corrosion of Nickel-Base Superalloys Used in Gas Turbine Engines", Final Report AFML-TR-67-306, Allison Division, General Motors, Indianapolis, Ind., Contract AF 33(615)-5211 (August 1967) DMIC No. 71222.
- (19) Bergman, P. A., Beltran, A. M., and Sims, C. T., "Development of Hot-Corrosion Resistant Alloys for Marine Gas Turbine Service", Final Report 2437, General Electric Company, Schenectady, N. Y., Contract N600 (61533)-65661 (October 1, 1967) DMIC No. 71304.
- (20) Seybolt, A. U., Bergman, P. A., and Kaufman, W., "Hot Corrosion Mechanism Study, Phase II", Final Report S-67-1170, General Electric Company, Schenectady, N. Y., Contract N600 (61533)-65595 (October 31, 1967) DMIC No. 71305.
- (21) Evans, E. W., and Hubbard, R. T. J., "Ignition and Burning of Binary Titanium Alloys", Report R/R/26/66, Imperial Metal Industries (Kynoch) Ltd., Birmingham, England (April 22, 1966) DMIC No. 70742.
- (22) "Accelerated Crack Propagation of Titanium by Methanol, Halogenated Hydrocarbons and Other Solutions", DMIC Memorandum 229, proceedings of a seminar held at Battelle Memorial Institute, Columbus Laboratories, Columbus, O., on March 6, 1967.
- (23) Kamber, K. T., Kendall, E. G., and Schieler, L., "Stress and Chemical Corrosion of Titanium Alloy in Freon Environments", Report TR-0158(3220-10)-3, Aerospace Corporation, El Segundo, Calif., Contract F04695-67-C-0158 (October 1967) DMIC No. 70904.
- (24) Judy, R. W., Jr., and Goode, R. J., "Stress-Corrosion Cracking Characteristics of Alloys of Titanium in Seawater", Interim Report 6564, Naval Research Laboratory, Washington, D. C., Contracts N00018-60(09), N00018-60(31), and N00014-66-00365 (July 21, 1967) DMIC No. 70931.
- (25) Huber, R. W., Goode, R. J., and Judy, R. W., Jr., "Fracture Toughness and Stress-Corrosion Cracking of Some Titanium Alloy Weldments", Welding Journal, 46 (10), 4398-4478 (October 1967) DMIC No. 70449.
- (26) Preliminary information reported by Douglas Aircraft Company, McDonnell Douglas Corporation, Newport Beach, Calif., under NASA Contract NAS 7-488.

- (27) Williams, J. C., "Some Observations on the Stress-Corrosion Cracking of Three Commercial Titanium Alloys", Transactions Quarterly, ASM, 52 (4), 446-600 (December 1967) DMIC No. 71139.
- (28) Fontana, M. G., "Stress-Corrosion Cracking of Metallic Materials", Report AFML-67-240, The Ohio State University, Columbus, O., Contract AF 33(613)-5108 (June 1967) DMIC No. 70150.
- (29) Fager, D. H., and Spurr, W. F., "Some Characteristics of Aqueous Stress Corrosion in Titanium Alloys", Report D6-60083, The Boeing Company, Renton, Wash., Contract N00014-66-C066 (September 1967) DMIC No. 70734.
- (30) Smith, H. R., Piper, D. E., and Downey, F. K., "A Study of Stress-Corrosion Cracking by Wedge-Force Loading", Report D6-19768, The Boeing Company, Renton, Wash., Contract N00014-66-C-0365 (June 1967) DMIC No. 70733.
- (31) Cavallaro, J. L., "Embrittlement of Titanium in Sewater", Report 2483, Naval Ship Research & Development Center, Annapolis, Md., (October 1967) DMIC No. 70387.
- (32) Weber, E. E., and Davis, A. O., "Stress Corrosion of Titanium Alloys Under Simulated Supersonic Flight Conditions", Report NASA CR-981, Lockheed-California Company, Lockheed Aircraft Corporation, Burbank, Calif., Contract NAS 1-6361 (December 1967) DMIC No. 70799.
- (33) Stone, L. H., and Freedman, A. M., "Cyclic Hot-Salt Stress Corrosion of Titanium Alloys", Summary Report NMA 67-151, Metals Division, Northrop Corporation, Hawthorne, Calif., Contract AF 33(613)-3642 (September 1967) DMIC No. 71112.

DMIC Reviews of Recent Developments present brief summaries of information which has become available to DMIC in the preceding period (usually 3 months), in each of several categories. DMIC does not intend that these reviews be made a part of the permanent technical literature. Copies of referenced reports are not available from DMIC, most can be obtained from the Defense Documentation Center, Cameron Station, Alexandria, Virginia 22314.

R. W. Endebrock, Editor